



IN REPLY REFER TO:

United States Department of the Interior

BUREAU OF LAND MANAGEMENT
CENTRAL REGION

Oil Shale Projects Office
131 N. 6th Street, Suite 300
Grand Junction, Colorado 81501
(303) 245-3960 FTS 245-6700

MEMORANDUM

TO: Files

February 24-25, 1983

FROM: John Miley

SUBJECT: U-a/U-b Tract Inspection

Personnel Present: Steve Navin Parsons
Conrad Parrish WRSOC
John Miley OSO

Primary Purpose of Inspection: Mining

Activities:

The decline was advanced to over 600'. Some harder quartzite lenses occurring in the siltstone have been causing some problems with the block mountings on the mining machine head. The machine was to be taken out for repair. Rock bolts and shotcrete extended to the face area. Conveyor parts had been received for installation in the decline.

The collar of the ventilation shaft was benched and was down approximately 15'.

xc: W. Hawes U-a/U-b
J. Godlove "
J. Goff "
~~L. Garrie~~ BLM
D. Evans ~~C. Smith~~ BLM
T. Portal UDOGM